Weft End Detection: Bobbin Sensor: Works On All Models And Make Of Circular Loom

- Minimum Tape Wastage
- Increase Operator's Efficiency
- Reduce Fabric Defects
- Increase Loom Efficiency
- Avoids Warp tape cutting due to Weft tape End


Easy to Replace Mounting Arrangements



Fixed type




Universal type



- Base Proxy and Logic PCB not Required
- Specially Designed for Loom

Mounting Arrangements



Fixed type




Semi Fixed type

Avoid Tape Waste





Different Colour Tape Bobbins



Maximum Utilization of shuttle tape



Different Types of Clamps




Black mat or Dark Blackish

Avoid Aluminum or Shining Pipe.
Use Dark/Black Mat Pipe

2) Direct Connectivity Option 24VDC Sensor PNP or NPN



1) Universal set 12V DC sensor with Relay PCB with clamp



This is for 1 Sensor.
For 2 Sensor use Dual Relay PCB



Beta Computronics Pvt. Ltd. 10/1 IT Park, Parsodi, Nagpur- 440022 (MS), INDIA
Phone: +91-712-2227125, 2240122, Mobile or WhatsApp : +91 - 9763711367
Website: www.betacomp.com E-mail: sandeep@betacomp.com, sales@betacomp.com

27 Years of Trust